

SAMO



RAWET



NMLS.Uxx		PXN, GXN, GXN200	
NMLS.	U01	0-20mV	A 0-20mA
NMLS.	U02	0-100mV	B 4-20mA
NMLS.	U03	0-1V	D 0-10V
NMLS.	U04	0-10V	E jiný
NMLS.	U05	0-100uA	F 0-5mA
NMLS.	U06	0-20mA	H -20...+20mA
NMLS.	U07	4-20mA	I -10...+10V
NMLS.	U08	-5...+5V	
NMLS.	U09	-10...+10V	
NMLS.	U10	-15...+15V	
NMLS.	U20	Jiný	

NMLS.PTxx		PXN30.A, ISOL600	
NMLS.	PT01	-100...100°C / Pt100	A 0-20mA
NMLS.	PT02	0...50°C / Pt100	B 4-20mA
NMLS.	PT03	0...100°C / Pt100	D 0-10V
NMLS.	PT04	0...200°C / Pt100	E jiný
NMLS.	PT05	0...600°C / Pt100	F 0-5mA
NMLS.	PT06	-100...100°C / Pt1000	H -20...+20mA
NMLS.	PT07	0...50°C / Pt1000	I -10...+10V
NMLS.	PT08	0...100°C / Pt1000	
NMLS.	PT09	0...200°C / Pt1000	
NMLS.	PT10	0...600°C / Pt1000	
NMLS.	PT20	jiný	

NMLS.Txx		PXN30.A, ISOL600	
NMLS.	TJ01	Tc"J" 0...800°C	A 0-20mA
NMLS.	TK01	Tc"T" 0...1000°C	B 4-20mA
NMLS.	TS01	Tc"S" 0...1600°C	D 0-10V
NMLS.	T20	jiný	E jiný
			F 0-5mA
			H -20...+20mA
			I -10...+10V

NMLS.Rxx			PXN30.A, ISOL600	
NMLS.	R01	0-100 Ohm	A	0-20mA
NMLS.	R02	0-1000 Ohm	B	4-20mA
NMLS.	R03	5-105 Ohm	D	0-10V
NMLS.	R20	jiný	E	jiný
			F	0-5mA
			H	-20...+20mA
			I	-10...+10V

NMLS.Fxx			ACM-FW	
NMLS.	F01	48-52Hz / 50..150V	A	0-20mA
NMLS.	F02	0-100Hz / 5-15V	B	4-20mA
NMLS.	F03	0-1000Hz / 5-15V	D	0-10V
<i>Na dotaz</i>		0,5 - 1Hz / 5-15V	E	jiný
NMLS.	R20	jiný	F	0-5mA
			H	-20...+20mA
			I	-10...+10V

NMLS.Mxx			ACN, ACM-I, ACM-U	
NMLS.	M01	0-110V AC	A	0-20mA
NMLS.	M02	0-150V AC	B	4-20mA
NMLS.	M03	0-35V AC	D	0-10V
NMLS.	M04	0-1A AC	E	jiný
NMLS.	M05	0-5A AC	F	0-5mA
<i>Na dotaz</i>		0-100mV AC	H	-20...+20mA
NMLS.	M20	jiný	I	-10...+10V

NMLS.XxxR1 a XxxR2Mxx

Nemáme ve výrobním programu.

Lze nahradit přístrojem DIGIREG03